NTSB ID: DEN03FA028 Aircraft Registration Number: N7989C

Occurrence Date: 12/29/2002 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place State Zip Code Local Time Time Zone
Steamboat Spgs CO 80477 1250 MST

Airport Proximity: Off Airport/Airstrip Distance From Landing Facility: Direction From Airport:

Aircraft Information Summary

Aircraft Manufacturer Model/Series Type of Aircraft
Piper PA-32-300 Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

### Narrative

 $\label{lem:conditions} \textbf{Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:}$ 

HISTORY OF FLIGHT

On December 29, 2002, at approximately 1300 mountain standard time, a Piper PA-32-300, N7989C, was destroyed when it impacted terrain while maneuvering near Steamboat Springs, Colorado. The commercial pilot and one passenger were seriously injured, another passenger received minor injuries; however, one passenger was fatally injured. The airplane was being operated under Title 14 CFR Part 91. Visual meteorological conditions prevailed for the personal, cross-country flight that originated from Bob Adams Field (SBS) Steamboat Springs, Colorado, approximately 20 minutes before the accident. No flight plan had been filed, but the pilot said he was en route to Canon City, Colorado.

The pilot said he had flown his three passengers and three dogs from Canon City, to Steamboat Springs, for Christmas celebrations. He said that on Thursday, December 26, he departed Steamboat Springs, on a solo flight back to Canon City, to fly parachutists up for jumps. He said that he flew the same departure path up Harrison Creek to cross Rabbit Ears Pass (elevation 10,007 feet). This flight was uneventful. On Saturday, he returned to Steamboat Springs to fly his passengers and dogs back to Canon City on the following day.

The pilot said he departed Steamboat Springs, at approximately 1230, on runway 32. He said that he headed south towards Rabbit Ears Pass, and was climbing to approximately 10,700 feet. He said that while flying up Harrison Creek, he encountered a "wind sheer or downdrafts," and the airplane would not clear the mountainous terrain. The pilot said he "decided to put the aircraft down in terrain with trees."

At 1304, a "9-1-1" call was made to the Routt County Sheriffs dispatch office by one of the passengers, reporting that the airplane had gone down. Search and rescue efforts were initiated, and the airplane was located at 1612 by two helicopters. Rescue workers arrived at the scene at 1700, and the pilot and three passengers were transported out by snowmobiles. The three dogs were rescued on the following day, December 30th, 2002.

A pilot at Steamboat Springs airport observed an airplane, matching the description of the accident airplane, depart at approximately 1245. He stated it looked "slow with a low angle of attack. It appeared to be laboring, and turned west and downwind with very shallow turns." He said "It just didn't look right. It appeared to be having difficulty climbing." Another witness, located in the valley approximately 2 miles west of the Harrison Creek mouth, said she heard a "loud airplane, which sounded like an 18 wheel truck using its Jake brake" flying low towards Harrison Creek. She said that it was between 1230 and 1300.

The fatally injured passenger had been trapped under debris of the airplane until the rescue team could cut her out. She died shortly after reaching the hospital in Steamboat Springs.

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

Occurrence Type: Accident

Narrative (Continued)

#### PERSONNEL INFORMATION

The pilot holds a commercial pilot certificate with airplane single and multiengine land, and instrument ratings. He also holds a basic ground instructor certificate, a mechanic's certificate with airframe and power plant ratings, and a senior parachute rigger's (back pack) certificate. He had accumulated 3,500 total hours of flight experience; 600 hours in make and model. The pilot also stated he had 6 hours of flight time in the airplane within the preceding 24 hours.

The pilot received a second-class FAA medical certificate on October 10, 2001. The certificate required that the holder wear lenses for distant vision and possess glasses for near vision.

#### AIRCRAFT INFORMATION

The airplane (S/N 32-7640051) was a single engine, propeller-driven, fixed landing gear, two seat airplane (normally a 6-place airplane, but 4 seats had been removed to allow parachute operations). It was manufactured by Piper Aircraft Company in 1975. It was powered by a Lycoming IO-540, six cylinder, reciprocating, horizontally opposed, direct drive, air cooled, fuel injected engine, which had a maximum takeoff rating of 300 horsepower at sea level. The last annual inspection was performed on April 10, 2002. At the time of the accident, the aircraft maintenance records and tachometer indicated that the airframe had accumulated approximately 8,597 hours. The airplane's current registration, in the pilot's name, was dated February 25, 1997.

On July 17, 1998, a Supplemental Type Certificate was issued for the "installation of a bolt-on departure bar assembly, handrail assembly and step assembly. This installation was approved for use in parachute jumping operations only." The most recent weight and balance measurement for the airplane was performed on January 19, 1999. "The airplane was in parachute jumper airlift configuration. Alteration was in accord with STC SA00352DE." The parachute jumper configuration involved removing the rear passenger seats and cargo door. In place of these seats was a piece of plywood with holes cutout for the seatbelts (this is where the fatally injured passenger was sitting).

The airplane's manufacturer representative said that the service ceiling of this aircraft was 16,250 feet.

### METEOROLOGICAL INFORMATION

At 1255, weather conditions at Hayden, Colorado (elevation 6,602 feet), 280 degrees 23 nautical miles (nm) from the accident site, were as follows: wind 270 degrees at 7 knots; visibility 10 statue miles (or greater); sky condition, clear; temperature 36 degrees Fahrenheit; dew point 18 degrees Fahrenheit; altimeter setting 29.69 inches.

According to search and rescue pilots flying Enstrom 280C piston powered helicopters in the area of the accident, there were "no unusual sinks or down drafts," and no turbulence was reported. A landowner, standing in front of her barn (approximately 6 nm west of the accident site at the mouth of Harrison Creek), said there was a "bit of a breeze directly out of the west." She estimated the wind to be approximately 14 to 18 knots.

The density altitude at the accident site (elevation 9,527 feet) was estimated to be 10,200 feet.

## WRECKAGE AND IMPACT INFORMATION

The airplane was found in a heavily forested, steep mountainous valley (elevation 9,527 feet; N40 degrees, 20.08 minutes; W106 degrees, 41.33 minutes). The conifer trees were up to approximately 18 inches in diameter and up to approximately 75 feet in height. An approximate 150 foot long

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

Occurrence Type: Accident

Narrative (Continued)

debris path (tree branches and aircraft parts) was oriented approximately 140 degrees (the Harrison Creek had a 085-265 degree orientation). The summit of Rabbit Ears Pass was 4 nm from the accident site, on a 010 degrees heading. To the north (340 degrees; 1 nm) of the accident site was Walton Peak, elevation 10,599 feet. The fuselage was found nearly upright (approximately 35 degrees right rotation), with both wings, and most of its horizontal stabilizer and elevator separated.

All of the airplane's major components were accounted for at the accident site. All the flight control surfaces were identified; flight control cable continuity was not possible due to impact damage. The left wing was found inverted in trees, approximately 25 feet above the ground. The wing spar's longitudinal axis was nearly level, and the leading edge was sloping approximately 35 degrees down. At approximately the midsection of the wing, a tree (approximately 12 inches in diameter) was imbedded in the wing. This impact arc extended from the leading edge aft to the main spar area. The main fuel tank was fractured, and the main landing gear was partially separated. The inverted left wing was found on the right side of the airplane's impact energy path.

The right wing was separated from the fuselage and broken into several pieces. The section forward of its main wing spar was separated. The fuel tank was fractured. The empennage displayed substantial impact damage, and only the vertical stabilizer and its rudder remained attached.

The fuselage was minimally deformed, but the occupiable space for the two front seat occupants was reduced considerably. The remaining seats had been removed during the STC conversion, and only sheets of plywood could be seen in the aft section of the fuselage.

Due to the deep snow and seasonal weather, the airplane wreckage was not recovered until June 10th, 2003. The engine and airframe were inspected on August 19th, 2003. Crankshaft, camshaft, and valve train continuity was verified. During the initial inspection, thumb compression was verified on all but number two cylinder. Its valve cover and rocker arms were removed, then thumb compression was obtained. One propeller blade was bent aft with some twisting, and the other blade displayed minimal back bending with significant twisting. Both blades exhibited chordwise striations and green transfer material. The yellow propeller spinner exhibited minimal damage.

No preimpact engine or airframe anomalies, which might have affected the airplane's performance, were identified.

# MEDICAL AND PATHOLOGICAL INFORMATION

Toxicology tests were not performed on the pilot due to his immediate medication and hospitalization.

# TESTS AND RESEARCH

According to one of the passengers, there were only two seats in the airplane. He and the fatally injured passenger were sitting on a "pad of some kind." The passenger reported he had a seat belt around him. According to Title 14 CFR Part 91.107, (a)(3), "Each person on board a U.S.-registered civil aircraft must occupy an approved seat or berth with a safety belt and, if installed, shoulder harness, properly secured about him or her during movement on the surface, takeoff, and landing."

A weight and balance calculation for the flight was performed using the airplane's last weight and balance data (January 19, 1999), and the occupants and the cargo weight which was acquired from interviewing the survivors. The airplane was certified for a maximum gross weight of 3,400 pounds, and center of gravity limits of 76 to 96.33 inches aft of datum. The airplane's gross weight (with occupants and cargo) at the time of the accident was estimated to be 3,280 pounds. The center of gravity limits at this weight were 88.30 to 96.33 inches. The calculated center of gravity of the airplane at the time of the accident was 98.66 inches, or 2.33 inches aft of the aft most limit. According to Title 14 CFR Part 91.9, (a) .....no person may operate a civil aircraft without

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

Occurrence Type: Accident

Narrative (Continued)

complying with the operating limitations specified in the approved Airplane or Rotorcraft Flight Manual, markings, and placards....."

A 3-D topographical study of Harrison Creek, by the Investigator-In-Charge, revealed a perpendicular ridge, orientated approximately 175 degrees jutting into Harrison Creek. The valley makes a semicircular diversion to the south, right at the impact area. The airplane was found on this southerly protruding ridge.

The Investigator-In-Charge determined that the 14 to 18 knot wind that was reported by the witness at the mouth of Harrison Creek, would have been blowing right up the creek. This would have made any airplane's ground speed just that much faster, and their rate of climb per mile would be correspondingly less.

#### ADDITIONAL DATA

The airplane, including all components and logbooks, was released to a representative of the owner's insurance company on January 18, 2003.

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

AVIATION			Occurrence Type: Accident										
Landing Facility/Approach Information													
Airport Name Airp			Airport I	ID:		riport Elevation Runway Us			Sed Runway Length		h	Runw	ay Width
Runway Surface Type: Unknown					·				·				
Runway Surface Condition: Unknown	own												
Type Instrument Approach: Unknown	own												
VFR Approach/Landing: Unknown	١												
Aircraft Information													
Aircraft Manufacturer Piper				odel/Se A-32-							erial Number 32-7640051		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Tricycle													
Homebuilt Aircraft? No	aft? No Number of Seats: 2				Certified Max Gross Wt.				3600 LBS Number			er of Engines: 1	
= - 11				Engine Manufacturer: Model/Serie Lycoming TIO-540						3:		Rated 300	d Power: HP
- Aircraft Inspection Information	- Aircraft Inspection Information												
Type of Last Inspection Da					Date of Last Inspection Time S				Since Last Inspection			Airframe Total Time	
Annual			04/20	04/2002				Hours			8348.8 Hours		
- Emergency Locator Transmitter (	ELT) Information												
ELT Installed? Yes ELT Operated? Yes					ELT Aided in Locating Accident Site? Ye						s		
Owner/Operator Information													
Registered Aircraft Owner	Stre	Street Address 426 S. Hancock Ave., Apt C											
Lloyd J. Moreau Jr.				City							State		Zip Code
	Stro	Colorado Springs Street Address									80903		
Operator of Aircraft	Olive	Same as Reg'd Aircraft Owner											
Same as Reg'd Aircraft Owner				City							State	Э	Zip Code
Operator Does Business As:			O	perator Desig	nator Co	ode:	•						
- Type of U.S. Certificate(s) Held:	None												
Air Carrier Operating Certificate(s)	:												
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 91: General Aviation													
Type of Flight Operation Conducted	d: Personal												
	]	FACT	UAL RE	EPOR	T - AVIATI	ON							Page 2

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name	City				State	Date of Birth	Age					
On File	On File	le			On File	On File	53					
Sex: M Seat Occupied:	wn	Certificate Number: On File										
Certificate(s): Commercial												
Airplane Rating(s): Multi	Airplane Rating(s): Multi-engine Land; Single-engine Land											
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): None												
Type Rating/Endorsement for Accident/Incident Aircraft?  Current Biennial Flight Review? 06/2002												
Medical Cert.: Class 2	Medica	al Cert. Status	S: Valid Med	dicalw/ wa	aivers/lim.							
	•											
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Actua	Instrument simulated		Rotorcraft	Glider	Lighter Than Air	
Total Time	3500	600	2600	800	60	0	200	50				
Pilot In Command(PIC)	3500	600	2600	800	60	0	200	50				
Instructor												
Last 90 Days		30										
Last 30 Days  Last 24 Hours	6	10 6	6				-+					
Seatbelt Used? Yes		lder Harness			Tox	icology P	arformed	12 No.		Second Pilot? N	2	
Gearbeit Oseu: Tes	31100	nuel Hairiess	Useu? INU		1102	ilcology 1	SHOTHEO	i: NO		become more 14	J	
Flight Plan/Itinerary												
Type of Flight Plan Filed: No	one											
Departure Point					Sta	State Airport Ide		dentifier Departu		arture Time	Time Zone	
Same as Accident/Incide		SBS			1240	)	MST					
Destination	Sta	State Airport I		ort Identifier								
Canon City	cc	CO 1V6										
Type of Clearance: None												
Type of Airspace: Class	G											
Weather Information												
Source of Briefing:  No record of briefing												
Method of Briefing: Unkno	wn											
FACTUAL REPORT - AVIATION Page 3												

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

	FIYBOR		Occ	urrenc	е Туре:	Accider	nt						
Weather	Information												
WOF ID	Observation Time	Time Zone	wor Elevation WOF Distance From Accid					dent Site	Direction From Accident Site				
HDN	1255	MST	66	02 Ft.	MSL				27 NM		Mag.		
Sky/Lowes	et Cloud Condition: Clea					Ft. AGL			Condition of Light: Day				
Lowest Ce	iling: None		Ft. AGL			ility:	10 SM		Altimeter:	29.69	"Hg		
Temperature: 2 °C Dew Point:				-8 °C Wind Direction: 270						Density Altitude:	7166	Ft.	
Wind Spee	Wind Speed: 7 Gusts:				Weather Condtions at Accident Site: Visual Conditions								
Visibility (F	RVR): Ft.	y (RVV)	SM Intensity of Precipitation:										
Restrictions to Visibility: None													
Type of Precipitation: None													
Accident Information													
Aircraft Damage: Destroyed				Aircraft Fire: None					Aircraft Explosion None				
Classificati	on: U.S. Registered/U	.S. Soil											
- Injury Su	mmary Matrix	Fatal	Serious	Minor	,	None	TOTAL						
First Pi	lot		1				1	]					
Second	d Pilot							]					
Studen	t Pilot							1					
Flight I	nstructor							1					
Check	Pilot							1					
Flight E	Engineer							1					
Cabin A	Attendants												
Other C	Crew							]					
Passer	ngers	1	2				3	[					
- TOTAL A	ABOARD -	1	3				4	1					
Other 0	Ground							1					
- GRAND	TOTAL -	1	3				4						

National Transportation Safety Board

# FACTUAL REPORT AVIATION

NTSB ID: DEN03FA028

Occurrence Date: 12/29/2002

Occurrence Type: Accident

# Administrative Information

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

Tom Forchtner FAA Denver FSDO Denver, CO 80249

Mike McClure Air Safety Investigator The New Piper Aircraft, Inc. Prosper, TX 75078

John B Butler Air Safety Investigator Lycoming Engines Arlington, TX 76014